

# Job Hazard Analysis


Tasks/Steps	Hazards Present	Safety Measures and Controls
Put on PPE before working with lab animals	None	Click here to enter text.
Clean caging	<p>Development of allergies from the animals and their bedding.</p> <p>Scratches, cuts, and bites from the lab animals</p>	<p>Wear proper PPE, including a particle mask and latex gloves to reduce the risk of developing allergies when cleaning rodent cages.</p> <p>Click here to enter text.</p>
Animal handling	<p>Development of allergies from the animals and their bedding.</p> <p>Scratches, cuts, and bites from the lab animals</p>	<p>Ask for assistance if needed</p> <p>Handle animals with proper procedure. Pick up rats and mice by the base of the tail, gently pinch crayfish by the carapace, just behind the cheliped. Move slowly and calmly around animals.</p> <p>Use gloves and a particle mask when handling rats and mice</p> <p>If you are bitten or scratched clean the wound immediately with warm, soapy water to prevent infection. Fill out an incident report (link in comment Tw 6.3382.2 (li4hly ))TJ (s)-4.3 (n)-</p>

---